## www.pce-group-europe.com





e-mail: info@industrial-needs.com

Phone. +44 ( 0 ) 2380 98703 0 Fax +44 ( 0 ) 2380 98703 9

# **MANUAL PCE-W3**





### 1. Application

Moisture Meter for Waste Paper is designed to rapidly determine the level of moisture contents of waste paper.

#### 2. Operation principle

Moisture meter measures the resi stance of the m aterial (waste paper). It has b een calibrated for normal composition of waste paper.

#### 3. Technical data

Range	6% - 30%
Power	9V, 1 battery 6F22
Electrode length	85 mm
Size	80 * 180 * 250 mm

#### Limitations

This warranty becomes null and void if you fail to pack you r PCE-W3 in a man ner consistent with the original product packaging and dam-age occurs during product shipment. This warranty does not cover: circumstance beyond our company's control; service required as the result of u nauthorized modifications or service; misuse, abuse; failure to follow our com pany operating or maintenance instructions. Repair or repla cement without charge is our company's only obligation under this warranty. Our company will not be responsible for any special, consequential or incidental damages resulting from the purchase, use, or improper functioning of this equipment regardless of the cause. Such damages for which our company's will not be responsible include, but are not limited to, loss of revenue or profit, downtime costs, loss of use of the equipment, cost of any substitute equipment, facilities of services, or claims of your customers for such damages.

#### **GUARANTEE**

The manufacturer guarantees the correct functioning of the Moisture Meter for Waste Paper PCE-W3 under normal use for a period of 12 months.

**( F** 

Serial number .....

Production date .....

In this direction will find a vision of the measurement technique: <u>http://www.industrial-needs.com/measuring-instruments.htm</u>

**NOTE:** "This instrument doesn't have ATEX protection, so it should not be used in potentially explosive atmospheres (powder, flammable gases)."